

a

charging the mold cavity with a plastic material;

axially displacing the blades having tab forming recesses therein relative to core from the female mold cavity to a predetermined position below the mold cavity and then rotating the cap relative to the core and blades to thereby position away from the blade recesses; and stripping the finished cap from the core.

[illegible]